



Ausfall der Kühlmittelpumpe

A close-up photograph of two dark, cast metal mechanical components, possibly pump housings or engine parts. The surfaces are heavily corroded, showing significant white and yellowish pitting and rust. The components have complex shapes with flanges, mounting holes, and internal structures. One component is in the foreground, and another is partially visible behind it to the right.

Stand 04.2021 **INA 0195** Technische Änderungen vorbehalten
Aufgeführte OE-Nummern dienen nur zu Vergleichszwecken
© 2021 Schaeffler Automotive Aftermarket GmbH & Co. KG

www.repxpert.de

REP>XPERT