



---

**Service Information / Informazioni di servizio / Información de servicio /  
Informação de Serviço**

Hinterachsgehäuse gegossen  
rear axle housing cast  
essieu arrière moulé  
asse posteriore diluviare  
eje trasero fundido  
Achteras behuizing gegoten  
Картер заднего моста, литой  
Obudowa tylnej wylane  
Arka aks muhafaza kalibi