

Important technical note relating to this unit

A software update was required to address charging issues.

Check the 7.5a fuse, no 15, under the dashboard has not blown. The ELD (Electronic Load Detector) can fail causing intermittent charging issues.