Certified Automotive Parts Association
Washington, DC

NOTIFICATION OF CAPA (Part No. / Part Lot) STATUS CHANGE

CAPA 零件號碼 / 批號狀態變更通知

Notification Number / 通知單編號:	16436					
Notification Date / 通知日期:	09/14/2011					
Participant Name / 廠商名稱:	Tong Yang Industry Co., Ltd					
Participant Address / 廠商地址:	No. 98, Sec. 2, An Ho Road Tainan R.O.C., 709					
Applicable CAPA Certification Standard / 適用之CAPA認證標準:	[X] CAPA 101	[ ] CAPA 201	[ ] CAPA 301	[ ] CAPA 501	[ ] CAPA 201A	[ ] CAPA 401
Participant Part Number / 零件號碼:	FD-10154AQ-RH					
Car Company Part Number / CCS 號碼:	9T1Z16005A	Partslink Number / 號碼:	FO1241279			
Part Description / 零件種類:	Fender R					

Application Description / 車種年份:						
	Make/ 車種:	Ford	Model/ 車型:	Transit	Years/ 年份:	10-11
	Make/ 車種:		Model/ 車型:		Years/ 年份:	
	Make/ 車種:		Model/ 車型:		Years/ 年份:	

Status Affects / 受影響狀態:	[X] Part Number / 零件編號	[X] Lot Number / 批號: 05/11A

Status as of this Notice / 通知後狀態: **NEW PART APPROVAL**

Reason for Status Change / 狀態變更原因:	[ ] Participant Request / 廠商要求	[ ] Production Inspection 產品檢驗	[ ] CAR / 改善措施要求
[ ] Random Material Testing 隨機抽樣材測	[ ] MM VTF / 市場觀察合車	[X] Other / 其他:	

Describe / 原因: NPA - passed dimension test.

Seal Size: / 標籤尺寸: [X] Standard / 標準 [ ] Alternative / 替代選擇

NOTE: When a part number is decertified or deleted, in order to re-enter the CAPA program, the Participant must register the part number using the New Part Registration Form and pay the applicable New Part Approval fee.

註 ：當整個零件號碼被取消認證或刪除時, 如欲將該零件重新加入CAPA認證計畫, 廠商必須送交新零件註冊登記表爲零件重新註冊, 並繳交新零件核可費用。

Submitted By / 提案人:		Issued By / 簽發者:	
	CAPA Validator		CAPA Administrator

© 2011 CAPA