

NOTICE OF STATUS (PART NUMBER/PART LOT) CHANGE FORM

CAPA 零件號碼 / 批號狀態變更通知

Notification Number / 通知單編號:	37243
Notification Date / 通知日期:	05/31/2019
Participant Name / 廠商名稱:	Tong Yang Industry Co., Ltd
Participant Address / 廠商地址:	No. 98, Sec. 2, An Ho Road, Annan District, Tainan 709
Participant Part Number / 零件號碼:	BZ-10085AQ-RH
(CCS) Part Number / 原廠零件編號:	2138800018
Partslink Number / 號碼:	MB1241164
Part Description / 零件種類:	Fender R
Application Description / 車種年份:	Mercedes-Benz E-Class, 17-18, Wagon

Note: Even though one application is identified on this form, if the part is used on multiple applications, all applications will apply.

備註: 廠商必須在本表上註明至少一種車種, 但如果零件可用於多個車種, 則所有車種都會列入註冊。

Applicable CAPA Certification Standard 101 Metals
/ 適用之CAPA認證標準:

Status Affects / 受影響狀態: Part Number / 零件編號 Lot Number / 批號: 05/19A

Status as of this Notice / 通知後狀態:

NEW PART APPROVAL

Reason for Status Change: 狀態變更原因:

Participant Request / 廠商要求 Production Inspection 產品檢驗 CAR / 改善措施要求

Random Material Testing 隨機抽樣材測 MM VTF / 市場觀察合車

Other - Describe: NPA – passed dimension test and closed out CAR #19-0684.
其他 - 請詳述:

When a part number is decertified or deleted, in order to re-enter the CAPA Certification Program, the Participant must register the part number using the New Part Registration Form and pay the applicable New Part Approval Fee.

註: 當整個零件號碼被取消認證或刪除時, 如欲將該零件重新加入CAPA認證計畫, 廠商必須送交新零件註冊登記表為零件重新註冊, 並繳交新零件核可費用。

Internal Use Only / 僅供內部使用

Submitted By / 提案人

Issued By / 簽發者

Brian Huang

Jillian Rahal