


**NOTIFICATION OF CAPA (Part No. / Part Lot) STATUS CHANGE**

CAPA 零件號碼 / 批號狀態變更通知

|  |   |  |   |
|--|---|--|---|
| Notification Number / 通知單編號:   | 18310   |  |   |
| Notification Date / 通知日期:  | 10/04/2012  |  |   |
| Participant Name / 廠商名稱:   | Tong Yang Industry Co., Ltd   |  |   |
| Participant Address / 廠商地址:  | No. 98, Sec. 2, An Ho Road Tainan R.O.C., 709                                       |  |   |
| Applicable CAPA Certification Standard / 適用之CAPA認證標準:  | <input checked="" type="checkbox"/> CAPA 101  | <input type="checkbox"/> CAPA 201                    | <input type="checkbox"/> CAPA 301   |
|  | <input type="checkbox"/> CAPA 501   | <input type="checkbox"/> CAPA 201A                   | <input type="checkbox"/> CAPA 401   |
| Participant Part Number / 零件號碼:  | AT-20016AQ  |  |   |
| Car Company Part Number / CCS 號碼:  | 41612754741   | Partslink Number / 號碼:                               | MC1230103   |
| Part Description / 零件種類:   | Hood  |  |   |
| Application Description / 車種年份:  | Mini Cooper Clubman R55, 08-11, S Model   |  |   |
|  | Mini Cooper Clubman R55, 09-11, John Cooper Works Model                             |  |   |
|  | Mini Cooper S Convertible, 09-10, John Cooper Works Model                           |  |   |
| Status Affects / 受影響狀態:  | <input checked="" type="checkbox"/> Part Number / 零件編號                              | <input checked="" type="checkbox"/> Lot Number / 批號: | 09/12A  |
| Status as of this Notice / 通知後狀  | <b>NEW PART APPROVAL</b>  |  |   |
| Reason for Status Change / 狀態變更原因  | <input type="checkbox"/> Participant Request / 廠商要求                                 | <input type="checkbox"/> Production Inspection 產品檢驗  | <input type="checkbox"/> CAR / 改善措施要求   |
| <input type="checkbox"/> Random Material Testing 隨機抽樣材測  | <input type="checkbox"/> MM VTF / 市場觀察合車  | <input checked="" type="checkbox"/> Other / 其他:      |   |
| Describe / 原因: <u>NPA – passed dimension test.</u>   |   |  |   |
| Seal Size: / 標籤尺寸:   | <input checked="" type="checkbox"/> Standard / 標準                                   | <input type="checkbox"/> Alternative / 替代選擇          |   |
| <p><b>NOTE:</b> When a part number is decertified or deleted, in order to re-enter the CAPA program, the Participant must register the part number using the New Part Registration Form and pay the applicable New Part Approval fee.</p> <p>註：當整個零件號碼被取消認證或刪除時，如欲將該零件重新加入CAPA認證計畫，廠商必須送交新零件註冊登記表為零件重新註冊，並繳交新零件核可費用。</p> |   |  |   |
| Submitted By / 提案人:  |  | Issued By / 簽發者:                                     |  |
|  | CAPA Validator  |  | CAPA Administrator  |