




NOTIFICATION OF CAPA (Part No. / Part Lot) STATUS CHANGE

CAPA 零件號碼 / 批號狀態變更通知

Notification Number / 通知單編號:	15571				
Notification Date / 通知日期:	02/09/2011				
Participant Name / 廠商名稱:	Tong Yang Industry Co., Ltd				
Participant Address / 廠商地址:	No. 98, Sec. 2, An Ho Road Tainan R.O.C., 709				
Applicable CAPA Certification Standard / 適用之CAPA認證標準:	☒ CAPA 101 ☐ CAPA 201 ☐ CAPA 301 ☐ CAPA 401 ☐ CAPA 501				
Participant Part Number / 零件號碼:	MZ-20036AQ				
Car Company Part Number / CCS 號碼:	GK2A52310D		Partslink Number / 號碼:	MA1230154	
Part Description / 零件種類:	Hood				
Application Description / 車種年份:	Make/ 車種:	Mazda	Model/ 車型:	6	Years/ 年份: 03-08
	Make/ 車種:		Model/ 車型:		Years/ 年份:
	Make/ 車種:		Model/ 車型:		Years/ 年份:
Status Affects / 受影響狀態:	☒ Part Number / 零件編號		☒ Lot Number / 批號: 11/10A		
Status as of this Notice / 通知後狀態:	NEW PART APPROVAL				
Reason for Status Change / 狀態變更原因:	☐ Participant Request / 廠商要求		☐ Production Inspection 產品檢驗		☐ CAR / 改善措施要求
☐ Random Material Testing 隨機抽樣材測	☐ MM VTF / 市場觀察合車		☒ Other / 其他:		
Describe / 原因: <u>NPA - passed dimension test.</u>					
Seal Size: / 標籤尺寸:	☒ Standard / 標準		☐ Alternative / 替代選擇		
NOTE: When a part number is decertified or deleted, in order to re-enter the CAPA program, the Participant must register the part number using the New Part Registration Form and pay the applicable New Part Approval fee. 註： 當整個零件號碼被取消認證或刪除時，如欲將該零件重新加入CAPA認證計畫，廠商必須送交新零件註冊登記表為零件重新註冊，並繳交新零件核可費用。					
Submitted By / 提案人:			Issued By / 簽發者:		
	CAPA Validator			CAPA Administrator	