

NOTICE OF STATUS (PART NUMBER/PART LOT) CHANGE FORM

CAPA 零件號碼 / 批號狀態變更通知

Notification Number / 通知單編號:	35410
Notification Date / 通知日期:	11/28/2018
Participant Name / 廠商名稱:	Gordon Auto Body Parts Co., Ltd.
Participant Address / 廠商地址:	No. 48, Neixi Road, Luzhu District, Taoyuan City 338
Participant Part Number / 零件號碼:	VGGF18FL1
Car Company Service (CCS) Part Number 原廠零件編號:	5G0821105B
Partlink Number / 號碼:	VW1240152
Part Description / 零件種類:	Fender L
Application Description / 車種年份:	Volkswagen E-Golf, 16, From 12-12-16

Note: Even though one application is identified on this form, if the part is used on multiple applications, all applications will apply.

備註: 廠商必須在本表上註明至少一種車種, 但如果零件可用於多個車種, 則所有車種都會列入註冊。

Applicable CAPA Certification Standard 101 Metals
/ 適用之CAPA認證標準:

Status Affects / 受影響狀態: ☒ Part Number / 零件編號 ☒ Lot Number / 批號: 11/18A

Status as of this Notice / 通知後狀態:

NEW PART APPROVAL

Reason for Status Change:
狀態變更原因:

☐ Participant Request / 廠商要求	☐ Production Inspection 產品檢驗	☐ CAR / 改善措施要求
☐ Random Material Testing 隨機抽樣材測	☐ MM VTF / 市場觀察合車	
☒ Other - Describe: NPA – passed dimension test. 其他 - 請詳述:		

When a part number is decertified or deleted, in order to re-enter the CAPA Certification Program, the Participant must register the part number using the New Part Registration Form and pay the applicable New Part Approval Fee.

註: 當整個零件號碼被取消認證或刪除時, 如欲將該零件重新加入CAPA認證計畫, 廠商必須送交新零件註冊登記表為零件重新註冊, 並繳交新零件核可費用。

Internal Use Only / 僅供內部使用

Submitted By / 提案人

Issued By / 簽發者


