


NOTIFICATION OF CAPA (Part No. / Part Lot) STATUS CHANGE

CAPA 零件號碼 / 批號狀態變更通知

Notification Number / 通知單編號:	17992		
Notification Date / 通知日期:	07/31/2012		
Participant Name / 廠商名稱:	Tong Yang Industry Co., Ltd		
Participant Address / 廠商地址:	No. 98, Sec. 2, An Ho Road Tainan R.O.C., 709		
Applicable CAPA Certification Standard / 適用之CAPA認證標準:	<input checked="" type="checkbox"/> CAPA 101	<input type="checkbox"/> CAPA 201	<input type="checkbox"/> CAPA 301
	<input type="checkbox"/> CAPA 501	<input type="checkbox"/> CAPA 201A	<input type="checkbox"/> CAPA 401
Participant Part Number / 零件號碼:	VW-10070AQ-RH		
Car Company Part Number / CCS 號碼:	5N0821106A	Partslink Number / 號碼:	VW1241141
Part Description / 零件種類:	Fender R		
Application Description / 車種年份:	Volkswagen Tiguan, 09-11		
Status Affects / 受影響狀態:	<input checked="" type="checkbox"/> Part Number / 零件編號	<input checked="" type="checkbox"/> Lot Number / 批號:	07/12A
Status as of this Notice / 通知後狀	NEW PART APPROVAL		
Reason for Status Change / 狀態變更原	<input type="checkbox"/> Participant Request / 廠商要求	<input type="checkbox"/> Production Inspection 產品檢驗	<input type="checkbox"/> CAR / 改善措施要求
<input type="checkbox"/> Random Material Testing 隨機抽樣材測	<input type="checkbox"/> MM VTF / 市場觀察合車	<input checked="" type="checkbox"/> Other / 其他:	
Describe / 原因: NPA - passed dimension test and closed out CAR # 12-0843.			
Seal Size: / 標籤尺寸:	<input checked="" type="checkbox"/> Standard / 標準	<input type="checkbox"/> Alternative / 替代選擇	
<p>NOTE: When a part number is decertified or deleted, in order to re-enter the CAPA program, the Participant must register the part number using the New Part Registration Form and pay the applicable New Part Approval fee.</p> <p>註：當整個零件號碼被取消認證或刪除時，如欲將該零件重新加入CAPA認證計畫，廠商必須送交新零件註冊登記表為零件重新註冊，並繳交新零件核可費用。</p>			
Submitted By / 提案人:		Issued By / 簽發者:	
	CAPA Validator		CAPA Administrator