


Product info sheet

Robert Bosch

0445120041

Special tools needed? Yes

Puller to remove inlet pipe



Product specific information

Programming No


Unlocking No

Adaption values reset No

Bleed No

adjustment at mounting_1 No

adjustment at mounting_2



Tightening torques

Bushing inlet pipe	Step 1: 80 Nm
Injector/ retaining clamp	
Straining screw inlet pipe	
Electrical connectors injector	2 Nm
High Pressure pipe nuts	1: 15 Nm 2: 45 Nm

Assembly instructions

Replace sealing washer

Replace inlet pipe

Core charge terms:

- externally intact,
- no mechanical damage,
- not dismantled,
- no heavy corrosion.

--	--	--	--