

# SKF Technical Bulletin

## Mandatory replacement of the Square-ring included in VKMC 06002 and VKPC 86810 kits



DACIA Sandero, Logan, RENAULT Clio, Modus, Twingo, NISSAN Kubistar



**Mandatory replacement of the Square-ring included in the Timing belt and water pump kits VKMC 06002 and VKPC 86810**



OE Nb: Renault: 77 01 478 923, 21 01 018 32R, 21 01 088 45R

Nissan: 21010-00Q1G, 21010-00QAK, 21010-00QAR

From the batch code 065N, the Square-ring is included in the Timing belt and water pump kits VKMC 06002 and VKPC 86810 kits.

**Note!** As it is necessary to re-use the original water pump housing connection, SKF has included a new Square-ring in the kits. The replacement of the sealing ring is mandatory to avoid leakage from the water pump housing connection.



VKMC 06002



VKPC 86810



**YouTube** [Click here to watch SKF technical videos on Youtube!](#)



© SKF Group 2017

The contents of this publication are the copyright of the publisher and may not be reproduced (even extracts) unless written permission is granted. Every care has been taken to ensure the accuracy of the information contained in this publication but no liability can be accepted for any loss or damage whether direct, indirect or consequential arising out of the use

