



## LuK Service Info

# Part Nr. 331 0071 15 – 310MM TDCA

Manufacturer: DEUTZ  
Art.-Nr.: 331 0071 15



**TB1264**

331 0071 15 replaces / ersetzt /  
remplace / sustituye a / sostituisce  
331 0071 14



631 3073 19 = 231 0020 17 + 331 0072 16

631 3073 11 = 231 0020 17 + 500 0076 11 + 500 0284 40 + 410 0045 40

631 3074 19 = 231 0020 17 + 328 0116 16


631 3074 11 = 231 0020 17 + 328 0116 16 + 500 0685 00 + 500 0679 00 + 410 0045 40

631 3075 10 = 231 0020 17 + 328 0116 16 + 500 0076 11 + 500 0284 40 + 410 0045 40

631 3076 10 = 231 0020 17 + 331 0072 16 + 500 0685 00 + 500 0679 00 + 410 0045 40


631 3080 09 = 131 0225 10 + 331 0071 15

631 3080 10 = 131 0225 10 + 331 0071 15 + 500 0685 00



331 0071 14

**SEE TB1239**



331 0071 15

Call : +44 (0) 1432 264264  
aftermarket.schaeffler.com

SCHAEFFLER  
**REP>XPERT**