



<b>PE-LS-0595</b>
☞ ☞ ⚙️ Ø10mm →12/94
<b>PE-DS-5041</b>
☞ ☞ ⚙️ Ø12mm 01/95→03/99 →RP 8151
<b>PE-LS-0592</b>
☞ ☞ ⚙️ Ø12mm RP 8151→ 03/99→

<b>CI-SB-6694</b>
☞ ☞ X Activa, Estate Ø22mm

<b>CI-SB-1307</b>	<b>CI-SB-1309</b>
☞	☞

<b>CI-SB-1308</b>
☞ ☞


<b>CI-TC-0160</b>	<b>CI-TC-0161</b>
☞	☞

<b>PE-BJ-3347</b>
☞ ☞

<b>PE-AX-5749</b>
☞ ☞ M14x1.5 X 2.0 Turbo, 2.1 TD, 3.0 v6, HDi
<b>PE-AX-0645</b>
☞ ☞ M16x1.5 ✓ 2.0 Turbo, 2.1 TD, 3.0 v6, HDi

<b>K150043</b>
☞ ☞ ✓ 1.8i (XU7JP)
✓ 1.9D (XUD9A/SD)
✓ 1.9TD (XD9T/TE/TY)
<b>K150122</b>
☞ ☞ X 1.6i, X 1.8i (XU7JP)
X 1.9D (XUD9A/SD)
X 1.9TD (XD9T/TE/TY)

<b>PE-ES-5723</b>	<b>PE-ES-5724</b>
☞ M14x1.5	☞ M14x1.5
<b>PE-ES-1668</b>	<b>PE-ES-1656</b>
☞ M16x1.5	☞ M16x1.5



<b>CI-RK-3569</b>
☞ ☞