






Atera SIGNO

BMW
5-er Limousine (F10) 03/2010–02/2017



nur bei / only for Part-No.: 045 173



- | | | |
|------------|-------------|--------------|
| 1- 074 110 | 7- 092 044 | 13- 092 181 |
| 2- 093 357 | 8- 087 886 | 14a- 095 612 |
| 3- 092 683 | 9- 093 491 | 14b- 095 613 |
| 4- 088 184 | 10- 095 603 | 14c- 095 613 |
| 5- 092 043 | 11- 092 198 | 14d- 095 612 |
| 6- 092 045 | 12- 087 909 | 15- 088 868 |




nur bei/only for
Part-No.: 045 173
16- 092 075
17- 093 110
18- 092 071



Atera SIGNO

BMW
5-er Limousine (F10) 03/2010 – 02/2017

Part-No. : 044 173
Part-No. : 045 173



Atera
MADE IN GERMANY





Atera GmbH
Im Herrach 1
D-88299 Leutkirch
Internet: www.atera.de



© ATERA GmbH
Ref.-Nr.: 044 173_060 860
Ref.-Nr.: 045 173_060 860
Stand/State: 06/02/2019 – Rev 00 Ver 03

Atera SIGNO

BMW
5-er Limousine (F10) 03/2010–02/2017



Atera SIGNO

BMW
5-er Limousine (F10) 03/2010–02/2017

