



LuK Service Info

Part Nr. 631 3117 10 – 310MM TSFA

Manufacturer: Landini

Art.-Nr.: 631 3117 10



TB1712

New product / Neues Produkt /
Nouveau produit / Nuevo produc-
to / Nuovo prodotto



631 3117 10 = 231 0116 10 + 331 0345 10 + 500 1343 40 + 500 063 40 + 410 0025 40



631 3117 10

Call : +44 (0) 1432 264264
aftermarket.schaeffler.com

SCHAEFFLER
REP>XPERT