

certificate

Thatcham
Research
www.thatcham.org



Vehicle Fit Tested
Annual
Production
Surveillance

www.tuv.com
ID 8900027457

This is to certify that:

100.18109
Bumper Front

Licence holder: Poliplast srl
Manufacturer Code: 4AEAD9DB0023
Vehicle test fitted in: Europe
Fits to: Volkswagen Caddy Van Kombi 2009 on M.P.V.

Part Image



Vehicle Image



Certified as having the following requirements successfully evaluated:

Vehicle Fit Tested, Production Surveyed

This certificate is only applicable for parts
which have the Thatcham TÜV Certified Part label attached

Date Issued
4th September
2014

Expiry Date
September
2016

Peter Shaw
Chief Executive
Thatcham Research

Certificate No:
TTC1185

Ralf Schunk
TÜVRheinland
Italia S.r.l

Experts in Safety, Security and Crash Repair

THE MOTOR INSURANCE REPAIR RESEARCH CENTRE

VOLKSWAGEN CADDY Van Kombi 2009 on

Poliplast Front Bumper


Compared To:

Original Front Bumper

VOLKSWAGEN CADDY Van Kombi 2009 on Original Vehicle Before Assessment



VOLKSWAGEN CADDY Van Kombi 2009 on
Under Bonnet Cross Dimensional Measurement




“X” Measures a distance of: 1346 mm

“Y” Measures a distance of: 1344 mm

Vehicle Within Required Tolerance

VOLKSWAGEN CADDY Van Kombi 2009 on
Under body Cross Dimensional Measurement



“X” Measures a distance of: 1091 mm

“Y” Measures a distance of: 1092 mm

Vehicle Within Required Tolerance

VOLKSWAGEN CADDY Van Kombi 2009 on Original Front Bumper



VOLKSWAGEN CADDY Van Kombi 2009 on POLIPLAST Front Bumper Fitted




POLIPLAST Front Bumper L/H




Original Front Bumper L/H



VOLKSWAGEN CADDY Van Kombi 2009 on



POLIPLAST Front Bumper R/H




Original Front Bumper R/H


POLIPLAST Front Bumper L/H



Original Front Bumper L/H



VOLKSWAGEN CADDY Van Kombi 2009 on



POLIPLAST Front Bumper R/H



Original Front Bumper R/H

