



OPEL INSIGNIA (11/13->)

EUROSTAMP S.r.l.
Via Airauda, 1 – 10044 Pianezza (TO) ITALY

Das Unternehmen erhält mit dem Zertifikat Nr. **B 15 07 66697 026.013** entsprechend dem dazugehörigen Prüfbericht das Recht, sein nachfolgend beschriebenes Produkt mit dem abgebildeten Prüfzeichen des

TÜV SÜD AUTOMOTIVE GmbH.

zu Kennzeichnung:



Dieses Produkt erfüllt die grundlegenden Anforderungen an Paßgenauigkeit, Passform und Material-/Splitterprüfung gemäß den Anforderungen der TÜV SÜD AUTOMOTIVE GmbH.

Produktbeschreibung: Stoßstange vorne Grundiert- mit 4 Löchern für die Sensoren

101.40.9130

den 11/06/2015

TÜV SÜD AUTOMOTIVE GmbH

Zertifikat – Nr.: B 15 07 66697 026.013
Certificate – No.

Anhang 1 Fotodokumentation
Annex 1 Photo documentation

Tested product



Original Equipment



Zertifikat – Nr.: B 15 07 66697 026.013
Certificate – No.

Original Equipment



Tested product




Zertifikat – Nr.: B 15 07 66697 026.013
Certificate – No.

Original Equipment



Tested product



Zertifikat – Nr.: B 15 07 66697 026.013
Certificate – No.

Original Equipment




Tested product



Zertifikat – Nr.: B 15 07 66697 026.013
Certificate – No.

Original Equipment	Tested product
	
	

Zertifikat – Nr.: B 15 07 66697 026.013
Certificate – No.

Original Equipment	Tested product
 A close-up photograph of the original equipment, showing a circular metal component with a serrated outer edge and a central opening, mounted on a white plastic base with two rows of small holes on either side.	 A close-up photograph of the tested product, showing a similar circular metal component with a serrated outer edge and a central opening, mounted on a white plastic base with two rows of small holes on either side.
 A side-view photograph of the original equipment, showing the circular metal component and the white plastic base with two rows of small holes on either side.	 A side-view photograph of the tested product, showing a similar circular metal component and the white plastic base with two rows of small holes on either side.
 A close-up photograph of the original equipment, showing a circular metal component with a serrated outer edge and a central opening, mounted on a white plastic base with two rows of small holes on either side.	 A close-up photograph of the tested product, showing a similar circular metal component with a serrated outer edge and a central opening, mounted on a white plastic base with two rows of small holes on either side.