



VOLKSWAGEN TIGUAN II (6/11 >)

EUROSTAMP S.r.l.
Via Airauda, 1 – 10044 Pianezza (TO) ITALY

Das Unternehmen erhält mit dem Zertifikat Nr. **B 16 11 66697 033.018** entsprechend dem dazugehörigen Prüfbericht das Recht, sein nachfolgend beschriebenes Produkt mit dem abgebildeten Prüfzeichen des

TÜV SÜD AUTOMOTIVE GmbH.

zu Kennzeichnung:



Dieses Produkt erfüllt die grundlegenden Anforderungen an Paßgenauigkeit, Passform und Material-/Splitterprüfung gemäß den Anforderungen der TÜV SÜD AUTOMOTIVE GmbH.

Produktbeschreibung: Stoßstange vorne Grundiert – mit Löchern für
Scheinwerferwaschanlange – mit 2 Löchern für die Sensoren und 2 Löchern für die PDC

153.29.9170


den 08/09/2016

TÜV SÜD AUTOMOTIVE GmbH

Zertifikat – Nr.: B 16 11 66697 033.018
Certificate – No.

Anhang 1 Fotodokumentation
Annex 1 Photo documentation

Original Equipment



Tested product



Zertifikat – Nr.: B 16 11 66697 033.018
Certificate – No.


Original Equipment



Tested product




Zertifikat – Nr.: B 16 11 66697 033.018
Certificate – No.

Original Equipment	Tested product
	
	
	

Zertifikat – Nr.: B 16 11 66697 033.018
Certificate – No.

Original Equipment	Tested product
	
	
	

Zertifikat – Nr.: B 16 11 66697 033.018
Certificate – No.

Original Equipment	Tested product
 A top-down view of a rectangular metal component. It features a central circular opening with a raised rim. On either side of this opening are two vertical columns of small, circular holes. The component is mounted on a larger metal plate.	 A top-down view of a similar rectangular metal component. It has a central circular opening and four small circular ports around it. The component is mounted on a larger metal plate with a grid pattern. The letter 'R2' is visible on the right side of the plate.
 A side view of the original equipment, showing its profile. It has a central circular opening and a small rectangular protrusion on the right side.	 A side view of the tested product, showing its profile. It has a central circular opening and a small rectangular protrusion on the right side.
 A close-up view of the central circular opening of the original equipment, showing a dark, reflective surface.	 A close-up view of the central circular opening of the tested product, showing a dark, reflective surface.

Zertifikat – Nr.: B 16 11 66697 033.018
Certificate – No.

Original Equipment	Tested product
	
	
	