



VOLKSWAGEN TOURAN III (5/10 >4/15)

EUROSTAMP S.r.l.
Via Airauda, 1 – 10044 Pianezza (TO) ITALY

Das Unternehmen erhält mit dem Zertifikat Nr. B 16 11 66697 033.011 entsprechend dem dazugehörigen Prüfbericht das Recht, sein nachfolgend beschriebenes Produkt mit dem abgebildeten Prüfzeichen des

TÜV SÜD AUTOMOTIVE GmbH.

zu Kennzeichnung:



Dieses Produkt erfüllt die grundlegenden Anforderungen an Paßgenauigkeit, Passform und Material-/Splitterprüfung gemäß den Anforderungen der TÜV SÜD AUTOMOTIVE GmbH.

Produktbeschreibung: Stoßstange hinten Grundiert mit 4 Löchern für die Sensoren
und 2 Löchern für die PDC

153.26.9660

den 08/09/2016

TÜV SÜD AUTOMOTIVE GmbH

Zertifikat – Nr.: B 16 11 66697 033.011
Certificate – No.

Anhang 1 Fotodokumentation
Annex 1 Photo documentation

Tested product



Original Equipment





Zertifikat – Nr.: B 16 11 66697 033.011
Certificate – No.

Original Equipment	Tested product
	
	
	

Zertifikat – Nr.: B 16 11 66697 033.011
Certificate – No.

Original Equipment	Tested product
	
	



Zertifikat – Nr.: B 16 11 66697 033.011
Certificate – No.

Original Equipment	Tested product
	
	
	

Zertifikat – Nr.: B 16 11 66697 033.011
Certificate – No.

Original Equipment	Tested product
	
	

Zertifikat – Nr.: B 16 11 66697 033.011
Certificate – No.

Original Equipment	Tested product
 A top-down view of a circular metal component, likely a door lock or latch, mounted on a metal plate. The component has a central circular opening and a surrounding flange with mounting tabs. The metal plate has some faint markings, including the number '5'.	 A top-down view of the tested product, which is a similar circular metal component. It is mounted on a metal plate with the number '5' and 'R2' visible. The component has a central circular opening and a surrounding flange with mounting tabs. A small wire is visible on the right side.
 A side view of the original equipment, showing the circular component mounted on a metal plate. The component has a central circular opening and a surrounding flange with mounting tabs.	 A side view of the tested product, showing the circular component mounted on a metal plate with the number 'L5' visible. The component has a central circular opening and a surrounding flange with mounting tabs. A small wire is visible on the right side.
 A front view of the original equipment, showing the circular component mounted on a metal plate. The component has a central circular opening and a surrounding flange with mounting tabs.	 A front view of the tested product, showing the circular component mounted on a metal plate. The component has a central circular opening and a surrounding flange with mounting tabs.

Zertifikat – Nr.: B 16 11 66697 033.011
Certificate – No.

Original Equipment	Tested product
