

Volkswagen Up 12- Original Vehicle Before Assessment



Volkswagen Up 12- Original Grille



Volkswagen Up 12- TONG YANG Grille





TYG Grille L/H



Original Grille L/H

Volkswagen Up 12-




TYG Grille R/H




Original Grille R/H

Volkswagen Up 12- TONG YANG Tow Eye Cover Fitting

Excess Material Preventing Correct Fitting Of Tow Eye Cover



Volkswagen Up 12- Original Tow Eye Cover Fitting




Volkswagen Up 12- TONG YANG Tow Eye Cover Fitting



Excess Material Preventing Correct Fitting Of Tow Eye Cover

Volkswagen Up 12- Original Tow Eye Cover Fitting



Volkswagen Up 12-

- Incorrect Fitting Of Tow Eye Cover (see slides 6-9)

- VTF Judgement: **FAIL**

Volkswagen Up 12- TONG YANG Tow Eye Cover Fitting After Tooling Modification



Volkswagen Up 12- TONG YANG Tow Eye Cover Fitting After Tooling Modification



Volkswagen Up 12-

- No Faults Identified
 - Comparative Fit Quality To Original
 - Previous Failure Issue Corrected
-
- VTF Judgement: **PASS**