

NOTICE OF STATUS (PART NUMBER/PART LOT) CHANGE FORM
CAPA 零件號碼 / 批號狀態變更通知

Notification Number / 通知單編號:	45923
Notification Date / 通知日期:	03/23/2021
Participant Name / 廠商名稱:	Gordon Auto Body Parts Co., Ltd.
Participant Address / 廠商地址:	No. 48, Neixi Road, Luzhu District, Taoyuan City 338
Participant Part Number / 零件號碼:	ADA619HD1
(CCS) Part Number / 原廠零件編號:	4K0823029B
Partslink Number / 號碼:	AU1230135
Part Description / 零件種類:	Hood
Application Description / 車種年份:	Audi A6, 19-21

 Applicable CAPA Certification Standard 101 Metals
 / 適用之CAPA認證標準:

Status Affects / 受影響狀態:
 Part Number / 零件編號
 Lot Number / 批號: 03/21A

Status as of this Notice / 通知後狀態:

NEW PART APPROVAL

Reason for Status Change: 狀態變更原因:	<input type="checkbox"/> Participant Request / 廠商要求	<input type="checkbox"/> Production Inspection 產品檢驗	<input type="checkbox"/> CAR / 改善措施要求
	<input type="checkbox"/> Random Material Testing 隨機抽樣材測	<input type="checkbox"/> MM VTF / 市場觀察合車	
	<input checked="" type="checkbox"/> Other - Describe: 其他 - 請詳述:	NPA – passed dimension test and closed out CAR #20-0919.	

When a part number is decertified or deleted, in order to re-enter the CAPA Certification Program, the Participant must register the part number using the New Part Registration Form and pay the applicable New Part Approval Fee.

註 : 當整個零件號碼被取消認證或刪除時, 如欲將該零件重新加入CAPA認證計畫, 廠商必須送交新零件註冊登記表為零件重新註冊, 並繳交新零件核可費用。

Internal Use Only / 僅供內部使用

Submitted By / 提案人	Issued By / 簽發者