



NOTICE OF STATUS (PART NUMBER/PART LOT) CHANGE FORM

CAPA 零件號碼 / 批號狀態變更通知

Notification Number / 通知單編號:	52530
Notification Date / 通知日期:	12/30/2022
Participant Name / 廠商名稱:	Gordon Auto Body Parts Co., Ltd.
Participant Address / 廠商地址:	No. 48, Neixi Road Taoyuan City 338
Participant Part Number / 零件號碼:	ADA321HD1
(CCS) Part Number / 原廠零件編號:	8Y0823029
Partslink Number / 號碼:	AU1230141
Part Description / 零件種類:	Hood
Application Description / 車種年份:	Audi A3, 21-22

Applicable CAPA Certification Standard 101 Metals / 適用之CAPA認證標準:

Status Affects / 受影響狀態: Part Number / 零件編號 Lot Number / 批號: 12/22A

Status as of this Notice / 通知後狀態: **NEW PART APPROVAL**

Reason for Status Change: 狀態變更原因:

Participant Request / 廠商要求 Production Inspection 產品檢驗 CAR / 改善措施要求

Random Material Testing 隨機抽樣材測 MM VTF / 市場觀察合車

Other - Describe: NPA – Passed all testing requirements. 其他 - 請詳述:

When a part number is decertified or deleted, in order to re-enter the CAPA Certification Program, the Participant must register the part number using the New Part Registration Form and pay the applicable New Part Approval Fee.

註：當整個零件號碼被取消認證或刪除時，如欲將該零件重新加入CAPA認證計畫，廠商必須送交新零件註冊登記表為零件重新註冊，並繳交新零件核可費用。

Internal Use Only / 僅供內部使用

Submitted By / 提案人	Issued By / 簽發者