



**NOTIFICATION OF CAPA (Part No. / Part Lot) STATUS CHANGE**

CAPA 零件號碼 / 批號狀態變更通知

|   |           |  |                        |   |                  |
|---|-----------|--|------------------------|---|------------------|
| Notification Number / 通知單編號:  |           | 13624  |                        |   |                  |
| Notification Date / 通知日期:   |           | 11/18/2009   |                        |   |                  |
| Participant Name / 廠商名稱:  |           | Taiwan Kai Yih Industrial Co., Ltd.  |                        |   |                  |
| Participant Address / 廠商地址:   |           | No. 202, Lane 250, Jian-An Road Tainan City R.O.C., 709  |                        |   |                  |
| Applicable CAPA Certification Standard / 適用之CAPA認證標準:   |           | <input checked="" type="checkbox"/> CAPA 101 <input type="checkbox"/> CAPA 201 <input type="checkbox"/> CAPA 301 <input type="checkbox"/> CAPA 401 |                        |   |                  |
| Participant Part Number / 零件號碼:   |           | BM-20014AQ   |                        |   |                  |
| Car Company Part Number / CCS 號碼:   |           | 41617111385  | Partslink Number / 號碼: |   | BM1230116        |
| Part Description / 零件種類:  |           | Hood   |                        |   |                  |
| Application Description / 車種年份:   | Make/ 車種: | BMW  | Model/ 車型:             | 5-Series  | Years/ 年份: 04-08 |
|   | Make/ 車種: | BMW  | Model/ 車型:             | 5-Series  | Years/ 年份: 06-08 |
|   | Make/ 車種: |  | Model/ 車型:             |   | Years/ 年份:       |
| Status Affects / 受影響狀態:   |           | <input checked="" type="checkbox"/> Part Number / 零件編號   |                        | <input checked="" type="checkbox"/> Lot Number / 批號: 11/09A   |                  |
| Status as of this Notice / 通知後狀態:   |           | <h1>NEW PART APPROVAL</h1>   |                        |   |                  |
| Reason for Status Change / 狀態變更原因:  |           | <input type="checkbox"/> Participant Request / 廠商要求  |                        | <input type="checkbox"/> Production Inspection 產品檢驗   |                  |
| <input type="checkbox"/> Random Material Testing 隨機抽樣材測   |           | <input type="checkbox"/> MM VTF / 市場觀察合車   |                        | <input checked="" type="checkbox"/> Other / 其他:   |                  |
| Describe / 原因: NPA - passed dimension test and closed out CAR # 09-0659.  |           |  |                        |   |                  |
| Seal Size: / 標籤尺寸:  |           | <input checked="" type="checkbox"/> Standard / 標準  |                        | <input type="checkbox"/> Alternative / 替代選擇   |                  |
| <p><b>NOTE:</b> When a part number is decertified or deleted, in order to re-enter the CAPA program, the Participant must register the part number using the New Part Registration Form and pay the applicable New Part Approval fee.</p> <p><b>註:</b> 當整個零件號碼被取消認證或刪除時, 如欲將該零件重新加入CAPA認證計畫, 廠商必須送交新零件註冊登記表為零件重新註冊, 並繳交新零件核可費用。</p> |           |  |                        |   |                  |
| Submitted By / 提案人:   |           | <br>CAPA Validator  |                        | Issued By / 簽發者:  |                  |
|   |           |  |                        | <br>CAPA Administrator |                  |