

INFORME DE RESULTADOS - VERIFICACIÓN ADAPTABILIDAD

RESULTS REPORT - VERIFIED FITTING

DATOS DE LA PIEZA PART DESCRIPTION			
Denominación: Name:	REJILLA INFERIOR IZQUIERDA CON ALOJAMIENTO DE FARO PARAGOLPES DELANTERO Front bumper left lower grille with holes for lamps		
Adaptable a: Adaptable to:	SEAT LEÓN (12)		
Fabricado por: Manufactured by:	PHIRA COMPONENTES AUTOMOCIÓN		
Ref. Fabricante: Manufacturer reference:	LE-12142	Ref. Constructor: O.E.M. reference:	5F0853665A9B9
Nº Certificación: Certification number:	19 081 19 12		



Valorando los resultados obtenidos en los ensayos y verificaciones a los que ha sido sometida la pieza de recambio, el dictamen final es:

Having analyzed the results of the test to which spare part has been subjected, the final decision is:

RESULTADO DE LA PIEZA:

Spare parts result:



Aprobada
Approved



Suspendida
Fail

INFORME DE RESULTADOS - VERIFICACIÓN ADAPTABILIDAD RESULTS REPORT - VERIFIED FITTING

ASPECTO VERIFICADO VERIFIED ASPECT	ENSAYO TEST	VALORACIÓN DECISION
ADAPTABILIDAD FITTING	Inspección visual Visual inspection	Cumple Requisitos CZ It is according to requirements of CZ
	Tiempo de Montaje Replacement time	Cumple Requisitos CZ It is according to requirements of CZ
	Proceso de trabajo Working process	Cumple Requisitos CZ It is according to requirements of CZ
	Montaje de accesorios Mounting accessories	No procede Not applicable
	Holguras Gaps	Cumple Requisitos CZ It is according to requirements of CZ
	Paralelismos Parallelism	Cumple Requisitos CZ It is according to requirements of CZ
	Alineaciones Alignment	Cumple Requisitos CZ It is according to requirements of CZ
		CONFORME APPROVED

ANEXO 1 - REPORTAJE FOTOGRÁFICO

ANNEX 1 – ADAPTABILITY PHOTO DOCUMENTATION



Muestra Constructor
O.E.M. Part

Muestra Fabricante
Spare Part

1 -



2 -



3 -

