


**NOTIFICATION OF CAPA (Part No. / Part Lot) STATUS CHANGE**

CAPA 零件號碼 / 批號狀態變更通知

Notification Number / 通知單編號:		17273	
Notification Date / 通知日期:		03/13/2012	
Participant Name / 廠商名稱:		Gordon Auto Body Parts Co., Ltd.	
Participant Address / 廠商地址:		No. 48, Nie-Shi Road Lu Chu Hsiang Taoyuan County R.O.C., 338	
Applicable CAPA Certification Standard / 適用之CAPA認證標準:		<input checked="" type="checkbox"/> CAPA 101 <input type="checkbox"/> CAPA 201 <input type="checkbox"/> CAPA 301 <input type="checkbox"/> CAPA 501 <input type="checkbox"/> CAPA 201A <input type="checkbox"/> CAPA 401	
Participant Part Number / 零件號碼:		BZCS07HD1	
Car Company Part Number / CCS 號碼:		2048801057	Partslink Number / 號碼: MB1230123
Part Description / 零件種類:		Hood	
Application Description / 車種年份:		Mercedes-Benz C-Class C230/C300/C350, 08-11	
Status Affects / 受影響狀態:		<input checked="" type="checkbox"/> Part Number / 零件編號 <input checked="" type="checkbox"/> Lot Number / 批號: 02/12A	
Status as of this Notice / 通知後狀態:		<h1>NEW PART APPROVAL</h1>	
Reason for Status Change / 狀態變更原因:		<input type="checkbox"/> Participant Request / 廠商要求 <input type="checkbox"/> Production Inspection 產品檢驗 <input type="checkbox"/> CAR / 改善措施要求	
<input type="checkbox"/> Random Material Testing 隨機抽樣材測		<input type="checkbox"/> MM VTF / 市場觀察合車 <input checked="" type="checkbox"/> Other / 其他:	
Describe / 原因: <u>NPA - passed dimension test and closed out CAR # 11-0141.</u>			
Seal Size: / 標籤尺寸:		<input checked="" type="checkbox"/> Standard / 標準 <input type="checkbox"/> Alternative / 替代選擇	
<p><b>NOTE:</b> When a part number is decertified or deleted, in order to re-enter the CAPA program, the Participant must register the part number using the New Part Registration Form and pay the applicable New Part Approval fee.</p> <p>註：當整個零件號碼被取消認證或刪除時，如欲將該零件重新加入CAPA認證計畫，廠商必須送交新零件註冊登記表為零件重新註冊，並繳交新零件核可費用。</p>			
Submitted By / 提案人:		Issued By / 簽發者:	
			
CAPA Validator		CAPA Administrator	