

**NOTICE OF STATUS (PART NUMBER/PART LOT) CHANGE FORM**
**CAPA 零件號碼 / 批號狀態變更通知**

Notification Number / 通知單編號:	35411
Notification Date / 通知日期:	11/28/2018
Participant Name / 廠商名稱:	Gordon Auto Body Parts Co., Ltd.
Participant Address / 廠商地址:	No. 48, Neixi Road, Luzhu District, Taoyuan City 338
Participant Part Number / 零件號碼:	VGGF18FR1
Car Company Service (CCS) Part Number 原廠零件編號:	5G0821106B
Partslink Number / 號碼:	VW1241152
Part Description / 零件種類:	Fender R
Application Description / 車種年份:	Volkswagen E-Golf, 16, From 12-12-16

Note: Even though one application is identified on this form, if the part is used on multiple applications, all applications will apply.

備註: 廠商必須在本表上註明至少一種車種, 但如果零件可用於多個車種, 則所有車種都會列入註冊。

Applicable CAPA Certification Standard 101 Metals  
/ 適用之CAPA認證標準:

Status Affects / 受影響狀態:  Part Number / 零件編號  Lot Number / 批號: 11/18A

Status as of this Notice / 通知後狀態:

## NEW PART APPROVAL

Reason for Status Change:  
狀態變更原因:

- |   |  |                                       |
|---|--|---------------------------------------|
| <input type="checkbox"/> Participant Request /<br>廠商要求  | <input type="checkbox"/> Production Inspection<br>產品檢驗 | <input type="checkbox"/> CAR / 改善措施要求 |
| <input type="checkbox"/> Random Material Testing<br>隨機抽樣材測                                      | <input type="checkbox"/> MM VTF / 市場觀察合車               |                                       |
| <input checked="" type="checkbox"/> Other - Describe: NPA – passed dimension test.<br>其他 - 請詳述: |  |                                       |

When a part number is decertified or deleted, in order to re-enter the CAPA Certification Program, the Participant must register the part number using the New Part Registration Form and pay the applicable New Part Approval Fee.

註: 當整個零件號碼被取消認證或刪除時, 如欲將該零件重新加入CAPA認證計畫, 廠商必須送交新零件註冊登記表為零件重新註冊, 並繳交新零件核可費用。

Internal Use Only / 僅供內部使用

Submitted By / 提案人

Issued By / 簽發者


